



CITY OF SAINT PAUL, MN

DEPARTMENT OF SAFETY AND INSPECTIONS

Steve Magner, Manager of Code Enforcement

Truth-in-Sale of Housing Report

This is a visual disclosure report based on the current City of Saint Paul Truth-in-Sale of Housing Evaluator Guidelines and is valid for one year from the date of issuance and for the owner named.

375 Jackson Street, Suite 220
Saint Paul, MN 55101-1806

Phone: 651-266-8989
Fax: 651-266-1919
Web: www.stpaul.gov/dsi

Property Address: 2325 CHILCOMBE AVE

Date of Evaluation: Jul 9, 2019

Date of Expiration: Jul 08, 2020

This report is intended to provide basic information to the home buyer and seller prior to the time of sale.

This report WILL NOT be used to enforce the requirements of the Legislative Code; however, it will be used to determine if there is compliance with the requirements for sale within the City of Saint Paul, MN.



MAJOR NOTIFICATIONS AND WARNINGS

For questions on these items, call the City's Information and Complaint Line at 651-266-8989

- Residential Type: Single Family Dwelling
- Smoke Detectors:
 - Smoke Detector Present: Y
 - Smoke Detector Properly Located: Y
 - Smoke Detector Hard Wired (required in Single Family Homes): Y
 - Smoke Detector Comments:
- Open Permits:

This property has the following open permits:

E - 15 004090 - - Active/Issued

HAZARDOUS

Garage(s)/Accessory Structure(s)

- Electrical wiring, outlets and fixtures

Plumbing System

- Floor drain(s) (basement)

Sleeping Room(s)

- Electrical outlets and fixtures

BELOW MINIMUM

Basement Only

- Electrical wiring, outlets and fixtures

Basement/Cellar

- Foundation
- Stairs and Handrails

Bathroom(s)

- Windows size/openable area/mechanical exhaust

Exterior Space

- Chimney(s)
- Drainage (grade)
- Roof structure and covering

Garage(s)/Accessory Structure(s)

- Garage door(s)
- Slab condition

Hallways, Stairs and Entries

- Stairs and handrails to upper floors

Plumbing System

- Gas piping (all floors)
- Waste and vent piping (all floors)
- Water heater(s), installation
- Water piping (all floors)

Report Rating Key (Where there are multiple rooms to a category, the Evaluator must specify the room to which a Comment is related)			
H: Hazardous Condition	B: Below Minimum	C: See Comments	M: Meets Minimum
Y: Yes	N: No	NV: Not Visible	NA: Not Applicable

CITY OF SAINT PAUL TRUTH-IN-SALE OF HOUSING REPORT

Address: 2325 CHILCOMBE AVE

File Number: File#: 19-061890

Date of Evaluation: Jul 9, 2019

Owner: Rebecca Buehrer Andrews/Gerhart J Bue

Zoning District: R3

Client Name: Rebecca & John Andrews

Present Occupancy:

Client Contact: Same

Number of Units Evaluated: Single Family Dwelling

Evaluator Name: Scott Scheunemann Scheunemann

Evaluator Contact: Work: 651-646-0009 scott.homeinspector@gmail.com

Basement/Cellar

- | | | |
|-------------------------------------|---|---|
| 1. Stairs and Handrails | B | 1. B - Uneven treads and risers. B - Lacking returned ends for handrail. B - Head room less than 6 feet 8 inches. |
| 2. Basement/Cellar Floor | M | |
| 3. Foundation | B | 3. B - Missing, cracks in block joints. |
| 4. Evidence of Dampness or Staining | Y | |
| 5. First Floor, Floor System | M | |
| 6. Beams and Columns | M | |

Electrical Services

- | | |
|-----------------------------------|---------|
| 7a. Number of Electrical Services | 1 |
| 7b. Amps | 200 |
| 7c. Volts | 120-240 |

Basement Only

- | | | |
|--|---|---|
| 8. Electrical service installation/grounding | M | 8. C - Wiring of interior of electrical panel is not part of TISH Evaluation. |
| 9. Electrical wiring, outlets and fixtures | B | 9. H - Knob & tube wiring in areas. B - Unsecured romex. |

Plumbing System

- | | | |
|--|---|--|
| 10. Floor drain(s) (basement) | H | 10. H - Floor drain clean out plug missing, drain must be functional with proper plug installed. |
| 11. Waste and vent piping (all floors) | B | 11. B - Deterioration at base of laundry wasteline. |
| 12. Water piping (all floors) | B | 12. B - Missing backflow preventer outside faucets. |
| 13. Gas piping (all floors) | B | 13. B - Obsolete gas valve installed for dryer. B - Damper installed in gas dryer exhaust vent. |
| 14. Water heater(s), installation | B | 14. B - Water heater supply valve is shared with humidifier. |
| 15. Water heater(s), venting | M | |
| 16. Plumbing fixtures (basement) | M | |

Heating System(s)

The Evaluator is not required to operate the heating plant(s) except during the heating season, between October 15 and April 15.

Report Rating Key (Where there are multiple rooms to a category, the Evaluator must specify the room to which a Comment is related)

H: Hazardous Condition	B: Below Minimum	C: See Comments	M: Meets Minimum
Y: Yes	N: No	NV: Not Visible	NA: Not Applicable

17a. Number of Heating Systems	1		
17b. Type	Forced Air		
17c. Fuel	Gas		
18. Installation and visible condition	M	18. C -Heat exchanger and internal components are not visible.	
19. Viewed in operation (required in heating season)	N		
20. Combustion venting	M	20. C - Plastic side vented design.	
21a. Additional heating unit(s): Type	NA		
21b. Additional heating unit(s): Fuel	NA		
21c. Installation and visible condition	NA		
21d. Viewed in operation	NA		
21e. Combustion venting	NA	21e.	
Kitchen			
22. Walls and ceiling	M		
23. Floor condition and ceiling height	M		
24. Evidence of dampness or staining	N		
25. Electrical outlets and fixtures	M		
26. Plumbing fixtures	M		
27. Water flow	M		
28. Window size/openable area/mechanical exhaust	M		
29. Condition of doors/windows/mechanical exhaust	M		
Living and Dining Room(s)			
30. Walls and ceiling	M		
31. Floor condition and ceiling height	M		
32. Evidence of dampness or staining	N		
33. Electrical outlets and fixtures	M		
34. Window size and openable area	M		
35. Window and door condition	M		
Hallways, Stairs and Entries			
36. Walls, ceilings, floors	M		
37. Evidence of dampness or staining	N		
38. Stairs and handrails to upper floors	B	38. B - Low guardrail. B - Lacking returned ends for handrail. B - Head room less than 6 feet 8 inches.	

Report Rating Key (Where there are multiple rooms to a category, the Evaluator must <u>specify the room</u> to which a Comment is related)			
H: Hazardous Condition	B: Below Minimum	C: See Comments	M: Meets Minimum
Y: Yes	N: No	NV: Not Visible	NA: Not Applicable

39. Electrical outlets and fixtures M

40. Window and door conditions M

Smoke Detectors

41a. Present Y

41b. Properly Located Y

41c. Hard-Wire Y

Bathroom(s)

42. Walls and ceiling M

43. Floor condition and ceiling height M

44. Evidence of dampness or staining N

45. Electrical outlets and fixtures M

46. Plumbing fixtures M

47. Water flow M

48. Windows size/openable area/mechanical exhaust B

48. B - No openable window or fan in basement bathroom.

49. Condition of windows/doors/mechanical exhaust M

Sleeping Room(s)

50. Walls and ceilings M

51. Floor condition, area and ceiling height M

52. Evidence of dampness or staining N

53. Electrical outlets and fixtures H

53. H - Ungrounded 3-prong outlets in East and NE bedrooms.

54. Window size and openable area M

55. Window and door condition M

Enclosed Porches and Other Rooms

56. Walls, ceiling and floor condition NA

57. Evidence of dampness or staining NA

58. Electrical outlets and fixtures NA

59. Window and door condition NA

Attic Space

60. Roof boards and rafters NA

60. C - Limited view from access hatch.

61. Evidence of dampness or staining NA

62. Electrical wiring/outlets/fixtures NA

63. Ventilation NA

Exterior Space

Report Rating Key (Where there are multiple rooms to a category, the Evaluator must specify the room to which a Comment is related)

H: Hazardous Condition	B: Below Minimum	C: See Comments	M: Meets Minimum
Y: Yes	N: No	NV: Not Visible	NA: Not Applicable

64. Foundation	M	
65. Basement/cellar windows	M	
66. Drainage (grade)	B	66. B - Grade doesn't allow surface water to drain away from building.
67. Exterior walls	M	
68. Doors (frames/storms/screens)	M	
69. Windows (frames/storms/screens)	M	
70. Open porches, stairways and deck(s)	M	
71. Cornice and trim(s)	M	
72. Roof structure and covering	B	72. B - Displaced shingle.
73. Gutters and downspouts	M	
74. Chimney(s)	B	74. B - Spalling brick.
75. Outlets, fixtures and service entrance	M	
Garage(s)/Accessory Structure(s)		
76. Roof structure and covering	M	
77. Wall structure and covering	M	
78. Slab condition	B	78. B - Slab cracked in areas.
79. Garage door(s)	B	79. B - Non fire rated service door to home.
80. Garage opener(s)	Y	
81. Electrical wiring, outlets and fixtures	H	81. H - Missing coverplate on outlet at opener.
Fireplace/Woodstove		
82. Number of Units	2	
83. Dampers installed	Y	83. C - Gas fireplace and wood burner.B - Damper was not operable in masonry fireplace.
84. Installation	NV	
85. Condition	NV	85. C - Flue and internal components are not visible.
Insulation		
86a. Attic Insulation: Present	Y	
86b. Attic Insulation: Type	Loose fiberglass	
86c. Attic Insulation: Depth	6-9 inches	
87a. Foundation Insulation: Present	N	
87b. Foundation Insulation: Type	NA	
87c. Foundation Insulation: Depth	NA	
88a. Knee Wall Insulation: Present	NA	
88b. Knee Wall Insulation: Type	NA	

Report Rating Key (Where there are multiple rooms to a category, the Evaluator must <u>specify the room</u> to which a Comment is related)			
H: Hazardous Condition	B: Below Minimum	C: See Comments	M: Meets Minimum
Y: Yes	N: No	NV: Not Visible	NA: Not Applicable

88c. Knee Wall Insulation: Depth NA

89a. Rim Joist Insulation: Y
Present

89b. Rim Joist Insulation: Type Foam

89c. Rim Joist Insulation: Depth 0-3
inches

89a. H - Exposed foam insulation poses a potential hazard in a fire.

General

90. Carbon Monoxide Alarm M

90. C - Plug in CO Alarm in hallway.

General Comments

LEGAL NOTICES:

Chapter 189 of the Saint Paul Legislative Code requires all single family, duplex, condo, townhouse and co-op homes for sale in the city to have a Truth-in-Sale of Housing disclosure report prepared and available to prospective buyers. A Truth-in-Sale of Housing disclosure report must be done for Contract-For-Deed sales.

A Truth-in-Sale of Housing (TISH) Disclosure Report in the City of Saint Paul is intended to provide basic information to the home buyer and seller prior to the time of sale. Failure to obtain a Truth-in-Sale of Housing disclosure report or failure to make that disclosure report available to prospective buyers, is a violation of law and is punishable as a misdemeanor carrying up to 90 days in jail and/or a \$1,000.00 fine.

A valid Truth-in-Sale of Housing disclosure report must be conspicuously displayed at the premises for all prospective buyers. TISH disclosure reports are also available online: <https://online.stpaul.gov/web/portal/public-search>

- This report WILL NOT be used to enforce the requirements of the Legislative Code; however, this evaluation form will be used to determine if there is compliance with the requirements for a hard-wired smoke detectors.
- This TISH report is based on the current Truth-in-Sale of Housing Evaluator Guidelines and is based upon different standards than the lender, Federal Housing Administration (FHA) or Veterans Administration (VA).
- This TISH is not warranted, by the City of Saint Paul nor by the evaluator for the condition of the building component, nor of the accuracy of this report.
- This TISH report covers only the items listed on the form and only those items visible at the time of the evaluation.
- The Evaluator is not required to operate the heating plant (except during the heating season), use a ladder to observe the condition of the roofing, disassemble items or evaluate inaccessible areas.
- This TISH report is valid for one year from the date of issue and only for the owner named on this report.
- If this building is used for any purpose other than a single family dwelling, it may be illegally zoned. To help you determine legal uses under the zoning ordinance, contact the Zoning Administrator at (651) 266-9008.
- Automatic garage doors should reverse upon striking an object. If it does not reverse, it poses a serious hazard and should be repaired or replaced immediately.
- All single family residences in Saint Paul must have at least one smoke detector connected to the electrical system (hard-wired). The detector must be located near sleeping rooms. For more information call Fire Prevention, (651)228-6230. (Saint Paul Legislative Code, Chapter 58.)
- Rainleaders connected to the sanitary sewer system must be disconnected. For more information call Public Works, Sewer Utility, and (651)266-6234.
- A house built before 1950 may have lead paint on/in it. If children ingest lead paint, they can be poisoned. For more information call Ramsey County Public Health, (651)292-6525.
- Neither the City of Saint Paul nor the Evaluator is responsible for the determination of the presence of airborne particles such as asbestos, noxious gases such as radon, or other conditions of air quality that may be present, nor the conditions which may cause the above.

Questions regarding this report should be directed to the evaluator. If you desire a reinspection and amended report, please contact your evaluator. They will perform a reinspection and file an amended report with the City of Saint Paul. The TISH evaluator may charge for this reinspection. Complaints regarding this report should be directed to Department of Safety and Inspections, Truth-in-Sale of Housing Program, Phone 651-266-8989.

Evaluator Statement:

I hereby certify I prepared this report in compliance with the Saint Paul Evaluator Guidelines, City of Saint Paul City Ordinance 189 and all other applicable policies and procedures of the Truth-in_Sale of Housing Board. I have utilized reasonable and ordinary care and diligence and I have noted all conditions found that do not conform to the minimum standards of maintenance. The report covers only those problems listed and reasonably visible at the time of my evaluation and does not warrant future useful life of any house component or fixture. I have included all required information pages with this report.

Evaluator Name: Scott Scheunemann Scheunemann Home Inspections

Phone: Work: 651-646-0009

Evaluation Date: Jul 9, 2019